



WUDCARE

STIR WELL BEFORE USE

Wudcare Floorboard Gap and Joint Filler is based on a flexible water-borne, non-yellowing acrylic resin. It is for use in combination with saw or sanding dust from carpentry work as a colour-matched filler for gaps of up to 2 mm between flooring boards and joints.

Preparation

Ensure surfaces are well sanded, clean and free from grease and contamination.

Application

Stir well before use. Add saved sawdust or sanding dust and mix into Wudcare Floorboard Gap and Joint Filler until a cream-like paste is created. Apply liberally to gaps or joints between floorboards with a stainless steel trowel.

Do not use at temperatures below 10°C or in conditions of high humidity.

Re-Coating Time

Wudcare Floorboard Gap and Joint Filler should be touch dry in a minimum of about 20 minutes, depending upon depth of filling, humidity and temperature, (min. application temp 10°C), and can be re-coated or sanded after that time.

A top coat of paint or varnish may be applied after a minimum of at least two hours.

Coverage

1 litre will cover approximately 7 - 10 square metres per coat depending on the absorbency of the surface.

(Coverage based on a 2mm wide gap).

Cleaning

Remove as much product as possible from application equipment whilst wet.

Clean equipment quickly with water. If the product is allowed to dry hard, then clean with Brush Restorer or Cellulose Thinners.

Disposal (pollution prevention)

Some local authorities have special facilities for disposal of waste paints, varnishes and coatings. Do not empty product into drains or watercourses.

Storage

Store in a cool dry place with lid tightly closed. Protect from frost.

Health and Safety

Warning

EUH208: Contains 5-chloro-2-methyl-2h-isothiazol-3-one. May cause an allergic skin reaction.

P272: Contaminated work clothing should not be allowed out of the workplace.

P280: Wear protective gloves/protective clothing/eye protection/face protection.

P102: Keep out of reach of children.

P261: Avoid breathing fumes.

P301+312: IF SWALLOWED: Call a POISON CENTRE or doctor if you feel unwell.

P302+352: IF ON SKIN: Wash with plenty of soap and water.



1 Litre e

Wudcare Products, 51 Waterloo Road,
London NW2 7TX UK.

Telephone: +44 (0)20 8450 4666

Fax: +44 (0)20 8452 2008

Email: info@wudcare.co.uk www.wudcare.co.uk